CUSTOMER SERVICE BULLETIN

Radio Shack®

CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	453Ø-3
Description	Scripsit
Model	Model II
Stock No.	26-453Ø Version 1.Øa
Date	February 19, 1981
Page 1 of	1

Problem

An error has been discovered in the storing of tabs in horizontal documents. The problem occurs when a tab stop is set on certain columns of the problem settings, the cursor would disappear and the system would lock up forcing the operator to RESET the computer. This does not damage anything on the disk! However, any text that had not yet been written to the disk is lost. The following patches fix this problem.

Solution

1. Reset your system and insert a Scripsit diskette.
2. Answer the Date prompt.
3. Press HOLD.
4. Answer the Time prompt.
5. At TRSDOS Ready, carefully enter the following patches.

```
PATCH SCRIPSIT A=9C9E F=78C621 C=CD3ØDC

PATCH SCRIPSIT A=9CB2 F=28Ø2F68ØD621 C=CD4ØDCØØØØØØ

PATCH SCRIPSIT A=DC3Ø F=ØØØØØØØØØØØØØØØØØØØØØØ C=78FE5F3ØØ3C621C9C642C9

PATCH SCRIPSIT A=DC4Ø F=ØØØØØØØØØØØØØØØØØØØØ C=28Ø5F68ØD642C9D621C9
```

6. Type STARTUP and press ENTER. Scripsit will load.
7. BACKUP the patched Scripsit disk!!