CUSTOMER SERVICE BULLETIN

Radio Shack®

CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4531-Ø9
Description	SCRIPSIT 2.Ø
Model	Model II
Stock No.	26-4531 Version 2.Ø
Date	June 4, 1982
Page 1 of	1

Problem

When using a user defined print code to define a character or characters such as (ç) or (ñ), the character(s) would not adhere to the current print mode (i.e. Bold, underline, double underline, etc.)

* * * THESE PATCHES ARE REQUIRED. * * *

Solution

The following patches will correct the problem:

Be sure the date at the bottom of the startup screen is Ø5/24/82. If not, be sure to obtain and do all previous patches.

```
PATCH SCRIPSIT/SYS R=163 P=196 F=F7F7 C=19D6

PATCH SCRIPSIT A=D619 F=ØØØØØØØØØØØØØØØØØØØØØØØØØØØØ
    C=78FE213ØØ4CDF7F7C9C53AFDDA

PATCH SCRIPSIT A=D626 F=ØØØØØØØØØØØØØØØØØØØØØØØØØØØØ
    C=ØEØ1CB5F28Ø43AFDDD4FCD35F9

PATCH SCRIPSIT A=D633 F=ØØØØ C=C1C9
```

After applying these patches, apply the following to change the date in the STARTUP screen:

```
PATCH STARTUP A=E4ØE F=BØB5AFB2B4 C=BØB5AFB2B7
```