## **CUSTOMER SERVICE BULLETIN**



Bulletin No.	47Ø7-Ø1
<b>Description</b>	RSCOBOL GENERATOR
Model	Model II/16
Stock No.	26-47Ø7 Ø1.Ø1.Ø1
Date	September 15, 1983
Page 1 of	1

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

## **Problem**

Necessary cosmetic changes to error messages and prompts within the program, use of pause and clear with data entry screens, subscreen data entry, the use of 3 and 4 alternate keys on Indexed Sequential files, and corrections to error messages when defining the length of report lines were incorporated in 700-2040.

\* \* THE FOLLOWING CHANGE IS REQUIRED! \* \*

## **Solution**

A bulletin was issued to customers advising them of the  $7\emptyset\emptyset-2\emptyset4\emptyset$  upgrade. The new version number after the  $7\emptyset\emptyset-2\emptyset4\emptyset$  upgrade is applied is  $\emptyset 1.\emptyset 1.\emptyset\emptyset$ . This bulletin is being issued for your information.