
Errata: Hardware Installation Manual for the Sun-3/50M

This errata introduces three minor changes to the Hardware Installation Manual for the Sun-3/50M:

- The first change is on the lower half of page 33. Below the caution referring to SCSI devices, please insert the following:

The above caution does NOT apply to systems with CPU's whose numbers are either 501-1162-12 or 501-1207-05 and later.

- The second change is on the lower half of page 52. Replace Table 3-6 *Fuse* with the following:

Table 0-1 *Fuses*

Base Unit AC Fuse size	Monitor Fuse size
7 A, Slo-Blo (for 115V)	1.5 A Slo-Blo (Moniterm)
4 A, Slo-Blo (for 230V)	1.6 A Fast-Blo (Phillips)

- The last change increases the maximum amount of on-board memory from 4 to 8MBs.