CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

Bulletin No. <u>4511-1</u>

Description Visicalc

Model

Model II

Stock No.

26-4511 Version 1.0

Date

April 8, 1981

Page 1 of

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

When printing reports with Visicalc the printer gives a set of extra line feeds.

Solution

The printer was rolled to the top of forms by hand. The way a top of forms should be done is / S E T <ENTER> <ENTER>.