

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	4515-06
<b>Description</b>	PROFILE PLUS
<b>Model</b>	Model II
<b>Stock No.</b>	26-4515 Ver. 01.00.00
<b>Date</b>	January 18, 1983
<b>Page 1 of</b>	1

### Problem

Patches on page 193, Profile Plus, 26-4515, are not sufficient to rename the main menu for hard disk users.

\* \* THE FOLLOWING PATCHES ARE OPTIONAL! \* \*

### Solution

After applying the patches on page 193 under "Patches Used to Rename Menus", add the following patches:

```
PATCH MENUPLUS/EFC A=722B F="M" C="x"  
PATCH MENUPLUS/EFC A=75EB F="MM" C="xx"
```

If the name A was used, the patch would be:

```
PATCH MENUPLUS/EFC A=722B F="M" C="A"  
PATCH MENUPLUS/EFC A=75EB F="MM" C="AA"
```