

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4515-08
Description	PROFILE PLUS
Model	Model II
Stock No.	26-4515 Ver 01.01.00*
Date	May 4, 1983
Page 1 of	1

### Problem

\* This Customer Service Bulletin applies to Version 01.01.00. See CSB 4515-07 for the same problem on Version 01.00.00.

Individual record suppression (CTRL-9) in detail lines of a report causes an unexpected title print every 249 records.

\* \* THE FOLLOWING PATCHES ARE REQUIRED! \* \*

### Solution

#### Version 01.01.00 of Profile Plus

To update the version number to 01.01.01, apply the following patch.

PATCH M A=3995 F=312E312E30202020 C="01.01.01"

For the problem, apply the following patches.

PATCH PRINT/EFC A=29F2 F=CAF929 C=CA355E

PATCH PRINT/EFC A=5E35 F=00000000000000000000000000000000 C=2A2B442B222B44C3F929

After patches from this Bulletin have been applied, the version number will be 01.01.01. Please make the necessary entry in your Version Log.