## **CUSTOMER SERVICE BULLETIN**

## Radio Shaek CUSTOMER SERVICE BULLETIN

Builetin No. 4912-05

Description TRSDOS II

Model Model 12/16

Stock No. 26-4912 Vers. 04.02.03

Date July 20, 1983

Page 1 of  $\frac{1}{2}$ 

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

## **Problem**

In the 4.2 FORMAT there is a problem that causes the system not to boot up when installed using the ALT=Ø option.

\* \* THE FOLLOWING PATCH IS REQUIRED! \* \*

## Solution

After patches from this Bulletin have been applied, the version number will be  $\emptyset4.\emptyset2.\emptyset4$ . Please make the necessary entry in your Version Log.

Apply the following patch to fix the problem.

PATCH FORMAT R=30 B=40 F=36 C=49

Apply the following patch to update the version number.

PATCH SYSTEM/SYS R=23 B=199 F=33 C=34