

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	4534-Ø1
<b>Description</b>	SCRIPSIT DICTIONARY
<b>Model</b>	Model II
<b>Stock No.</b>	26-4534 Version 1.Ø
<b>Date</b>	August 27, 1982
<b>Page 1 of</b>	1

### Problem

When using the SCRIPSIT DICTIONARY to "flag" a word, the "flag" routine returns with the code for BREAK, when a 3-letter word is flagged.

\* \* THIS PATCH IS REQUIRED! \* \*

### Solution

1. In Drive Ø, insert a SCRIPSIT 2.Ø system diskette which has 26-4534 software installed on it.
2. At TRSDOS READY, key in the following patch.  

```
PATCH SCRIPSIT/RST A=E317 F=26ØØ C=AF67
```
3. From SCRIPSIT, make a backup copy of the diskette that has been patched.
4. Execute SCRIPSIT 2.Ø as normal.